











NÁVOD NA MONTÁŽ ŠATNÍKOVEJ SKRINE CO-3DS


ZOZNAM KOMPONENTOV

A = 1 KS 	B = 2 KS 	C = 1 KS 	D = 1 KS 		E = 1 KS 
			F = 1 KS 		
G = 1 KS 					
1 M6 x 30 = 28 KS 	2 M4 x 25 = 3 KS 	3 35 x 35 = 3 KS 	4 4 x 30 x 60 = 1 KS 	5 M4 x 20 = 4 KS 	


KROK 1




KROK 2




KROK 3



KROK 4



KROK 5



KROK 6

